
090 / 091 TEKMAR SENSOR





Special Requirements

Must be mounted on a level slope,

so that 090/094 sensor is flush with slab surface.

Maximum Wire Lengths for Snow / Ice Sensor 090

The following table shows the maximum wire length for the Snow / Ice Sensor 090.

The "Max Added Length" column shows the additional length of wire that can be added to the 090's existing 65'.


All splices must be:


soldered individuallyheat shrinked individually


• located in a dry junction box, preferably inside the building

For a more robust connection and long term signal quality, it is recommended to heat shrink the cable lacket

Maximum wire length for 090				
AWG olid copper wire)	Max. Added Length (feet)	Total combined feet, including factory 65'		
10	2787	2852		
12	1760	1825		
14	1103	1168		
16	692	757		
18	435	500		
20	276	341		







PF					
REV	DESCRIPTION		DATE	В\	
DRAWN BY:		CHE	CHECKED BY:		
DATE:		SCAL	.E:		
00/00/21			N/A		

SHEET:

2.0

TITLE:

PEDESTAL MOUNT SECTIONDETAILS